



---


**PARTS CATALOG**  
**99944200221 3-Line**  
**Rapid Loader Head**

**Cutting Head**

***ECHO, INCORPORATED***

400 Oakwood Road Lake Zurich, Illinois 60047 USA

WWW.ECHO-USA.COM



ITEM	PART NUMBER	QTY	DESCRIPTION	REMARKS
1	P022001130	1	TOP COVER	
2	P022001120	1	BOTTOM COVER	
3		3	SHAFT	INCLUDED IN REPAIR KIT - P/N P022001091
4	P022001080	1	EYELET	
5		3	SPRING	INCLUDED IN REPAIR KIT - P/N P022001091
6	-----	3	CAM	INCLUDED IN REPAIR KIT - P/N P022001091
7	-----	6	SCREW	INCLUDED IN REPAIR KIT - P/N P022001091
	P022001091	1	REPAIR KIT	INCLUDES 3 OF EACH
	P022001100	1	COLLET ASSORTMENT (7 PCS.)	NOT SHOWN
	P022001110	1	HARDWARE PACK	NOT SHOWN



**ECHO, INCORPORATED**

400 Oakwood Road  
Lake Zurich, IL 60047 USA

[WWW.ECHO-USA.COM](http://WWW.ECHO-USA.COM)

---